

Strikotherm Spongefloat Render SILICAAT

Product Name:

Strikotherm Spongefloat Render SILICAAT

Composition:

High-quality, factory made decorative finishing plaster based on high-grade binder and water glass, natural fillers and tested additives for improving adhesion and workability.

Colors:

White and the relatively light colours from the Strikolith colour range (minimum brightness value 40%).

Use:

Strikotherm Spongefloat Render SILICAAT is mainly used outdoors as a decorative sponge plaster.

Technical data:

- Density: approx. 1.7 kg/cm³
- pH: approx. 11

Surface preparation:

Treat the surface with Strikotherm Primer Silicaat and allow it to dry completely (at least 72 hours).

Surfaces:

The surface must be sound and stable, free of dust, loose fragments, form oil, moisture or any other contaminants that could interfere with adhesion.

General Processing:

First mix well and, if necessary, dilute with up to 2% clean tap water. Apply the first layer of Strikotherm Spongefloat Render SILICAAT at single-grain thickness with a stainless steel trowel. After about 24 hours apply the second layer of Strikotherm Spongefloat Render SILICAAT (again at single grain thickness) and smooth it out flat. After it has dried somewhat, sand it evenly with a fine scouring sponge. To stop blemishes from forming, it should be complexly sanded-down with a scouring sponge. Small colour variations may occur as a result of variations in weather and processing conditions. Clean tools with water immediately after use. Protect Strikotherm Spongefloat Render SILICAAT against the effects of weather both during and after processing. For exterior use, always overpaint Strikotherm Spongefloat Render SILICAAT with Strikolith Silicaatcoat or Strikolith Pearlcoat.

Consumption:

Approx. 3.5 kg/m².

Storage:

Storage life is about 6 months if kept dry.

Safety:

It is advisable to adequately protect eyes and skin with personal protective equipment while using mineral plasters. If Strikotherm Spongefloat Render SILICAAT comes into contact with the eyes, rinse immediately with plenty of clean water (for about 15 mins). Then consult a doctor.

Particularities:

The use of additional additives is not permitted. Do not process if the air and surface temperature is below 5°C (41°F) or if frost or temperatures above 30°C (86°F) are expected. Protect Strikotherm Spongefloat Render SILICAAT against the effects of weather while it is being applied. Clean tools with water immediately after use.